


## **BOSS PRODUCTS**


A Division of Northern Star Industries, Inc. P.O.Box 787 Iron Mountain MI 49801-0787 www.bossplow.com






Step 1. C10040

Follow instructions one side at a time or the blade could fall causing injury. Remove Trip Return Springs (4) Pushframe to Attachment Bar 5/8" x 4" Bolt (6) and 5/8" Nut (5).




Step 2. G10649

Assemble Bumper Stop (7) onto Attack Angle Adjustment Bracket (8) using 1/2" Full Nuts (9) one on either side of bracket.



Step 3. G10650

Reassemble mounting bracket first using existing 5/8 Bolt (6) and Nut (5). Attach Trip Return Spring (4) using 8" eyebolt (10) with 1/2" Flat Washer (2) and 1/2" Nylon Lock Nut (1). Repeat for other side.



Step 4.

G10651

To adjust stop loosen Trip Spring and extend Bumper Stop. Retighten Bumper Stop and retighten Trip Spring.