



TGS1100/TGS600 Wiring Diagram



TGS1100/TGS600 Wiring Diagram



KEY

WHITE (12 GA): 12V TO SPINNER MOTOR
 BROWN (12 GA): +12V TO SPINNER MOTOR

