## Hydraulic Valve Application History

	Description		Manifold											
Valve		HYD12280	HYD12270	HYD07092	HYD07091	HYD07090	HYD07065*	HYD07044	HYD07045	HYD07019	HYD01602	STB03097	STB03006	
HYD01637	Valve, Lift / Angle	6	2	6	2	2	2	6	2	2	6	6	3	
HYD07047	Valve, SmartHitch Attach			1	1		1	1						
HYD07048	Valve, Flow Control			1	1		1	1	1	1				
HYD01639	Valve, Relief V-Blade (2800psi)	2		2				2			2		2 (1500PSI)	
HYD01640	Valve, Check	4	1	4	1	1	1	4	1	1	3	4		
HYD01638	Valve Coil	6	4	7	4	2	2	7	2	2	6	6	4	
HYD01647	Valve Ground Strap						2	7	2	2	6	6	4	
HYD07059	Coil Nut	6	3	6	3	2	2	6	2	2	6	6	4	
HYD07060	Coil Nut (SmartHitch Valve)			1	1			1						
	# 10 Hydraulic Valve, Angle Cartridge					1	,		,	,				
HYD07029	(3 Position - 4 Way Spool)					Red Manifold	1		1	1				
LIVDOZGOZ	Relief Valve, Hydraulic Crossover		4		4	4	4		4	4				
HYD07027	(3800 PSI)		1		1	1	1		1	1				
HYD07030	Coil, Hydraulic Valve - used with					1	2		2	2				
111007030	valve HYD07029					Red Manifold	2		2	2				
HYD07032	Ground Strap, Hydraulic Valve Dual - used with valve HYD07029						1		1	1				
	used with valve 111 bor 029						·							
HYD07100	#8 Hydraulic Valve, Angle Cartridge		1		1	1								
	(3 Position - 4 Way Spool)					Green Manifold								
	Notes Control											,		
HYD01641	Valve Screen Cartridge										1	1		
	Valve, Relief Straight Blade													
STB03096	(3800 PSI)											2		
	(3000 F31)													
STB03060	Valve, 2 Pos / 4 Way												1	
3100000	Vaivo, 27 05/4 vvay													

Note: HVI - SH201 Hydraulic Manifolds have no servicable parts. The manifold must be completely replaced with HYD01602. Distinguishing marks: HVI engraved on manifold block, white valve coils, (does not have a removable ground strap).

<sup>\*</sup> HYD07065 is the same valve block as HYD07045, except HYD07047 SmartHitch valve is installed at the factory.